

Product Change Notification ID#0116

Title of notification

Information - Firmware update in 3G/GNSS module - CrossLink AI

Level of Change

- Product Change Notice – Customer Information
- Product Change Notice – Customer Approval
- Product Change Notice – Customer Action
- End of Life Issue – Required Customer Action
- Errata – Customer information

Affected Products

#	Product Part Number	Product Name	Revision after change
1	C000138-30	CrossLink AI	1.2
2	C000040-214	Starter kit CrossLink AI	1.2
3	S-10122	CrossLink AI	1.2

Product Attribute Affected

- Material Change
- Design Change
- Software Change
- Other: 3G/GNSS Firmware get additional functionality.
- Process Change
- Data Sheet Change
- Packing/Shipping Change

Impact of Change

- | | | |
|-------------------------------------|----------|---------------------------------------|
| <input type="checkbox"/> | Form | No change in form |
| <input type="checkbox"/> | Fit | No change in fit |
| <input type="checkbox"/> | Function | Change in function, description below |
| <input checked="" type="checkbox"/> | Other: | See description below |

Description of Change(s)

1. We have received information from the manufacturer of the 3G / GNSS component used in this product that there will be some additional firmware functionality in next delivery of the component. See attached document.

Reason for Change(s)

1. Manufacturer updated component firmware to version R03A17.

Recommendation

This PCN is for customer information.

Products will get new revision to track the change. See above.

Estimated Change Date

First deliveries with new firmware estimated to January 2020.

Contacts

Stefan Eriksson

Phone: +46 271 75 76 85

E-mail: Stefan.eriksson@crosscontrol.com