

Product Change Notification ID#0115

Title of notification

Information about a problem using the Config_setOnOffTriggerMode function in CCPilot VS.

Level of Change

- Product Change Notice – Customer Information
- Product Change Notice – Customer Approval
- Product Change Notice – Customer Action
- End of Life Issue – Required Customer Action
- Errata – Customer information

Affected Products

#	Product Part Number	Product Name	Revision after change
	C000139-212	CCPilot VS	N/A
	S100139-212		
	S024139-212		
	S022139-212		
	S020139-212		
	S002139-212		

Product Attribute Affected

- Material Change
- Design Change
- Software Change
- Other: -
- Process Change
- Data Sheet Change
- Packing/Shipping Change

Impact of Change

- Form No change in form
- Fit No change in fit
- Function Change in function, description below

Description of Change(s)

N/A

Reason for Change(s)

N/A

Recommendation

We recommend all developers to avoid using the Config_setOnOffTriggerMode function or ccsettingsconsole to set the CONFIG_ONOFF_LEVEL_TRIGGER mode with SS version 1.0.0.0 or earlier. Doing so will make the device inoperable and it must be sent in for repair. The OnOffTriggerMode functionality works with SS version 1.1.0.0 or later.

It is not likely that this problem ever occurs in operation but it could be used by mistake during development of applications which will render the device inoperable.

Estimated Change Date

An update that solves this problem will be available in the October-November 2019 timeframe.

Contacts**Lars Olsson**

Phone: +46 271 75 76 95

E-mail: lars.olsson@crosscontrol.com